


# Vacuum sensors

- -1 to +10 bar
- Analog and/or Digital Outputs
- With display



## Sensors


	Pressure range	Output	Connection		Order code
			electrical	pneumatic	
	-1 to 0 bar	1 analog / 7 amp.	conn.	G1/8	<b>P5V-SVVA16K</b>
	-1 to 0 bar	1 analog & 1 digit	M8	G1/8	<b>MPS-V1G-PC</b>
	0 to +10 bar	1 analog & 1 digit	M8	G1/8	<b>MPS-P1G-PC</b>
	-1 to 0 bar	1 analog & 1 digit	M8	Flange	<b>MPS-V1E-PC</b>
	0 to +10 bar	1 analog & 1 digit	M8	Flange	<b>MPS-P1E-PC</b>
	-1 to 0 bar	1 digit	M8	Flange	<b>MPS-V1E-PC3</b>
	-1 to 0 bar	2 digit	M8	G1/8	<b>MPS-V2G-PC</b>
	0 to +10 bar	2 digit	M8	G1/8	<b>MPS-P2G-PC</b>
	-1 to 0 bar	2 digit	M8	G1/8	<b>MPS-V3G-PC</b>
	0 to +10 bar	2 digit	M8	G1/8	<b>MPS-P3G-PC</b>
	-1 to 0 bar	2 digit	M8	Tube	<b>MPS-V6T-PC</b>
	-1 to 0 bar	2 digit	Cable	Tube	<b>MPS-V6T-PG</b>
	-1 to 0 bar	2 digit	M8	G1/8	<b>MPS-V6G-PC</b>
	-1 to 0 bar	2 digit	Cable	G1/8	<b>MPS-V6G-PG</b>
	-1 to 0 bar	1 analog	Cable	Tube	<b>MPS-V6T-AGE</b>
	0 to +10 bar	1 analog	Cable	Tube	<b>MPS-P6T-AGE</b>
	-1 to 0 bar	1 digit	M8	Tube	<b>MPS-V8T-PC</b>
				Cable	<b>MPS-71E-PG</b>
			Cable	<b>MPS-74E-PG</b>	

# Vacuum accessories


- High performance silencers and vacuum filters
- Electronic cables with M8 connector 4 pin




## Electronic cables

Order code
 <b>CB-M8-4P-2M</b>
<b>CB-M8-4P-5M</b>
<b>CB-M8-4P-5M-90</b>


## Silencers


Thread	Order code
 G 3/4	<b>MS6-01</b>
G 1/2	<b>MSL02</b>
G 1/4	<b>MSM-01</b>
G 1/8	<b>MSS-01</b>

## Vacuum filters

Order code
 <b>VF-11</b>
<b>VF-2</b>
<b>VF-3</b>
<b>VF-5</b>
<b>VF-6</b>
<b>VFL-44</b>
<b>VFL-66</b>

## Vacuum cut-off valve

Thread	Order code
 M5	<b>P5V-BKS35</b>
G1/8	<b>P5V-BKS11</b>
G1/4	<b>P5V-BKS12</b>

Thread	Order code
 G3/8	<b>P5V-BKS13</b>
G1/2	<b>P5V-BKS14</b>